

Engaged, effective leadership critical to well-being of plant staff, contractors

afety has taken center stage in the electric power industry. It is now one of the top three discussion topics at virtually all user-group meetings serving gas-turbine (GT) owner/operators. Another way to gauge the industry's safety consciousness is to visit www. ccj-online.com and compare the number of safety and O&M entries in the **COMBINED CYCLE Journal's Best** Practices Awards program this year with those from five years ago. In 2008 there were more than twice as many entries in the O&M category than there were in safety; this year, there were one-quarter more safety entries than O&M.

The open discussion sessions at the annual HRSG User's Group meeting focus strictly on the technical aspects of heat-recovery steam generators, leaving safety off the main program. But with upwards of half the user attendees first-timers, many of whom are new to the industry and may not be aware of how just how seriously plant managers view safe work practices, Chairman Bob Anderson worked a primer on the subject into the Maintenance Workshop conducted the day before the "main event" last February 28-29 at the Hilton Americas in Houston, Tex.

Anderson, a principal at Floridabased Competitive Power Resources Corp and former plant manager at Progress Energy steam and combined-cycle plants, was the right person to handle this assignment. His goal was "awareness," not to conduct a safety course. He told the editors he would have been surprised if industry veterans didn't know almost all of the safety dos and don'ts included in his presentation, "Identifying—and Avoiding—Combined-Cycle Hazards," but believed his commonsense approach to safety would be of value to the "recruits."

Developing a safety culture

Anderson began by telling the group of about a hundred users that building and nurturing a safety culture is a prerequisite for operating and maintaining a safe plant. He defined "safety culture" as a constant commitment to safety that permeates the entire organization. But while this is



Safety equipment should be inspected by a qualified plant employee before each use, regardless of vendor certifications. Each piece of gear should have a permanent tag/number to assure meaningful record-keeping. *Astoria Gas Turbines*



Mobile filter cart and piping modifications allow ground level access to circ-water-pump motor lube sump making hazard-free a job that had been dangerous. *Allegheny Energy Units 3, 4, 5*




Inlet filter house floor, originally made of steel plate, was replaced with steel deck grading to prevent snow drifting in winter which blocked air flow and to eliminate a slip hazard. *Beatrice Power Station*



Ammonia-tank leak-suppression system protects plant personnel and neighbors. Water spray system, which has 34 nozzles configured on six lines surrounding the tank, was designed to NFPA

an essential step, he continued, it is only one of several.

Another essential step: Identify the real-world hazards present in the plant and implement practical procedures to avoid them. Anderson said that based on his experience, the specifics of these procedures are best managed at the plant level, not by safety professionals at headquarters. This is particularly challenging at thinly staffed combined-cycle plants,



- 1. Place on firm flat surface
- 2. Place order with OEM

3. **WAIT...**

- 4. Follow instructions in circle
- 5. Repeat step 4 as necessary

A Better Alternative

The ultimate resource for GE Speedtronic spares.

Mk I, Mk II, Mk IV, Mk V, EX2000, MkVI, EX2100

Spare Parts | Testing and Repairs | Field Service Training | Asset Recovery



GAS TURBINE CONTROLS CORP.

914.693.0830 | gasturbinecontrols.com | sales@gasturbinecontrols.com

he added, where the onsite safety leader usually has multiple responsibilities.

Other safety challenges at combined-cycle plants may include inexperienced personnel and a heavy reli-

ance on contractors. Many technicians and operators come from other industries and are generally unfamiliar with powerplant operations, Anderson said. Plus, with the typical combined-cycle complement numbering two dozen or fewer personnel, you don't have the relevant expertise on staff to handle anything much beyond routine maintenance.


Odds are contractors will be unfamiliar with your plant and its safety best practices and may require comprehensive indoctrination for certain assignments, as well as continuous oversight by plant employees.

Categories of hazards

To discuss the specific hazards found in combined-cycle plants in an organized manner, Anderson sorted them into these five categories:

- Hazards created by "merely moving around."
- Uncontrolled release of fluids.
- Controlled release of fluids.
- Hazards during normal plant configurations.
- Hazards during abnormal plant configurations.

Don't wait for varnish to develop in your Lube Oil System!



STATIC DISCHARGE

Reliable, trip-free servo-valve performance

- Varnish-free lube and hydraulic circuits
- Extended oil life
- Decreased bearing and gear wear

Products for a Cleaner World

HILCO Turbine Oil Conditioning Systems Prevent Varnish Formation

HILCO's system addresses the root causes of oil degradation with a three-fold combination of purification methods: coalescence to remove free water, vacuum degasification to remove dissolved gasses, & filtration with antistatic filter elements to eliminate static discharge. Start-up failures and unit trips caused by sticky servovalves can be brought under control!

> Hilco PH-CGJ style filter elements incorporate conductive fibers which are co-pleated in between two layers of hi performance microglass filter media.As a result the Hilco anti-static filter element dissipates static charge build up before discharge can occur.



The Hilliard Corporation 100 West 4th Street Elmira, NY 14902 607-733-7121 Fax 607-733-0928 hilliard © hilliardcorp.com www.hilliardcorp.com



Safety shed protects personnel against severe weather. Jasper Generating Station

"Merely moving around" hazards include trips, falls, burns, chemical inhalation, eye contamination, hearing damage, etc. They are the easiest hazards to avoid, through conscientious use of hard hats, eye and ear protection, respiratory gear, proper footwear, gloves, good housekeeping, good lighting, etc. Unfortunately, Anderson noted, these are the hazards that also are the easiest to overlook because you walk by them daily and become complacent about the dangers they pose.

Because such hazards often are hard for site personnel to identify because "everything looks normal," plant managers may use the buddy system for auditing. This is how it works: Plant A sends three or four of its most safety-conscious employees to Plant B—and vice versa—to conduct an audit with a "fresh eye." Sharing of ideas and experiences is especially productive.

The hazard in this first category with, perhaps, the most lethal potential is the confined space. Moving into such areas as HRSG casings, steam drums, condenser steam side, etc, before they are properly vetted can lead to serious injury or death. In particular, the confined-space atmosphere must be checked to assure sufficient oxygen to support life and the absence of poisonous/explosive gases.

The photos distributed throughout this article illustrate ways plants are mitigating "merely moving around" hazards. The generating plants identified received Best Practices Awards within the last three years for sharing their ideas with the global community of gas-turbine users. You can access many more safety best practices by using the search function available at www.ccj-online.com.

Uncontrolled release of fluids. Combined-cycle plants require the movement of large quantities of combustion air, steam, exhaust gas, fuel gas, oil, and water. Most often, these fluids contain high levels of energy because of their mass flow rates, pressures, and/or temperatures. Thus their uncontrolled release presents



Permanent platform provides safe access to gas-turbine igniters. *Granite Ridge Energy*



Safety permit stations are strategically located on the deck plates. They are easily accessible and highly visible. *Granite Ridge Energy*

Proven Protection and Safety

FM/FMC/ATEX/IECEx Approved Explosion-Proof Solenoids and FM Approved Safety Shut-Off Valves





Location of emergency showers is clearly identified with decals on walkways. Alarm sounds when shower is in use. *Mint Farm Generating Station*

a significant safety hazard to onsite personnel.

Anderson said the most common source of uncontrolled fluid release is a pressure-boundary breach caused by material failure. Typically, the fluid release is sudden, violent, noisy, and accompanied by substantial movement of equipment and structural components.

Those in the immediate area of an uncontrolled release, he continued, can be injured or killed by asphyxiation, burning, scalding, falling, or being struck by flying debris. Injuries also have occurred while the startled worker is franticly trying to escape the area.

Shifting into high gear, Anderson appeared to have the group's undi-



vided attention. "Although we cannot precisely predict *when* an uncontrolled energy release might occur," he said, "we can precisely predict *where*. As plant leaders we need to identify the specific locations in our facilities that are most vulnerable and take steps to minimize personnel risk. All employees and contractors should be made aware of these areas so they can avoid them when possible and be mindful of a safe means of egress whenever they need to work there."

High-energy steam piping was one of the areas of concern mentioned by the former plant manager. He had a special respect for joints where dissimilar metals or P91 materials are welded, noting that both the P91 material and its welding are intolerant of any deviation from proper thermal treatment. If you see steam or condensate escaping from a pipe's lagging, Anderson said, "Leave the area and report your finding to the control room immediately." An immediate precautionary shutdown is in order. Do not remove insulation to investigate the leak while the pipe is still pressurized.

The speaker mentioned several other places where uncontrolled releases of steam might occur in quick succession. When he got to steamdrum manway gaskets, he paused. Many plants continue to suffer gasket failures, Anderson noted, and continue to experiment with different solutions. "But this is a serious safety problem and no place for a trial-anderror approach. The manway door and the gasket, together, comprise an engineered system that must be properly designed, operated, and maintained according to the OEM's specifications."

Steam is not the only dangerous fluid, Anderson said, shifting gears. Uncontrolled releases of hot gases also present serious hazards, he said. Specific locations where vigilance is necessary include the following:

- GT exhaust duct/HRSG expansion joints, which protect against the release of exhaust gas at temperatures up to 1200F.
- Duct penetration seals.

Advanced surface coatings for turbomachinery

More high-performance coatings, more experience, more innovation, more options and more support



Send your parts to us...

Turbine parts need to withstand corrosion, wear and intense heat at elevated temperatures. Our surface-enhancement solutions address these challenges and more, enabling you to:

- Improve engine performance
- Decrease energy consumption
- · Extend component life and maintenance intervals

Get more information:

Call (713) 849-9474 in the U.S. Call +44 (0) 7976 643370 outside the U.S. Visit www.praxairsurfacetechnologies.com. © 2012 Praxair S.T. Technology Inc. All rights reserved.



...or let us come to you.


Let us bring our coating services to you with Axxess[™] on-site coating. Only Praxair can apply advanced coatings at your plant. Anywhere in the world. When you coat on-site, you'll:

PRAXA

SURFACE TECHNOLOGIES

- Shorten outage duration
- Reduce risk of part damage







Penetrations on enclosures eliminate the need to run lines, cords, and leads through doorways. Walter M Higgins Generating Station



Highly visible numbers (18 \times 18 in.) at all key entrances to plant save time in directing emergency response units to the proper location. The numbers should be high enough off the ground that the line of sight cannot be blocked by deliveries, parked vehicles, etc. *Granite Ridge Energy*

- Flanges, valves, fittings, and heat exchangers—especially in the fuel gas system, where temperatures may be 350F and pressures 700 psig.
- Gas-turbine flanges, expansion joints, valves, and fittings. Example: Compressor bleed air may reach temperatures up to about 700F.
- Exhaust stack drains, which could release flue gas at up to about 300F during normal operation, higher temperatures during startup.

Don't forget, too, the speaker went on, that uncontrolled releases of seemingly harmless fluids like compressed air and water can cause injury. Examples: Debris sent airborne by the sudden release of a fluid, the whipping action of an unsecured compressed-air hose, flashing of pressurized hightemperature water when the pressure boundary is compromised, etc.

Controlled releases of fluids

also are of concern. They may be sudden and unanticipated, as with the lifting of safety-relief valves; or planned, as with the opening of vents and drains. Either can pose a safety hazard because the actual point of fluid release typically is far from the actual valve or vent.


A contractor may be standing near the safety-relief discharge, unaware that a steam-pressure excursion is about to cause an automatic lifting of that valve. Or a plant operator manually opening vent valves may not know that a mechanic happens to be tackling an unrelated maintenance job, right near that vent's discharge point.

Safety-relief valves pose yet another concern. They often are surrounded by a large cloud of steam, hot water, and debris because of the inherent gaps in the valve upper body, discharge nozzle, and vent/stack connection. If such a cloud envelops a nearby walkway, a normal egress route might be blocked.

As with an uncontrolled release of fluids discussed previously, you can reduce the risks associated with controlled releases by identifying the specific locations in your plant that are most vulnerable and making them well known to staff and contractor personnel.

Normal plant configurations. Plant systems typically are lined-

 $\textbf{COMBINED CYCLE} \ \textbf{JOURNAL}, \ \textbf{Second Quarter} \ 2012$



DCS RETROFITS

AS-BUILT DRAWINGS FACTORY ACCEPTANCE TESTING COMMISSIONING PROJECT MANAGEMENT

OVATION/WDPF OPTIMIZATION

RELIABILITY ENHANCEMENTS ALARM MANAGEMENT TRAINING TUNING SERIAL INTERFACES

Process Control Solutions IIc.

WWW.PROCESSCONTROLSOLUTIONSLLC.COM

601-310-1686



Steps and landings replaced the standard ladder system to facilitate safe access to gas turbine's combustor section. Rokeby Generating Station



Roof hatch over bearing tunnel facilitates confined-space rescue. Edward W Clark Generating Station

up in one of a handful of normal, well-understood configurations. This facilitates such plant operations as GT ignition and loading, steam system warm-up and loading, plant shutdown, and overnight layup. As the plant O&M team gains experience, it naturally becomes competent and comfortable with the normal configurations and procedures.

However, Anderson said, as a person with supervisory responsibilities, you must ensure that the staff's comfort zone does not expand into complacency because there are many hazards associated with a normal plant configuration.

For example, many components are energized automatically by the control system or remotely by a control-room operator challenged by time constraints and revenue goals. Although intentional, the sudden actuation of valves, pumps, turbine shafts, and compressors can injure personnel near the equipment who are caught unaware. Components may actuate unintentionally as well because of equipment malfunction or operator error.

Both intentional and unintentional events often produce startlingly loud



plant personnel against arc-flash hazards. Gateway Generating Station

Flash suit protects

noise, which can cause permanent hearing loss to an unprotected worker or plant visitor. Hazards attributed to equipment failure or operator error include:

Water hammer, which can initiate pipe or structure movement, sudden noise, flying or falling debris, release of fluids, etc.

Gas-path explosions caused by inadequate engine purge also is characterized by sudden noise. Other hazards include the release of exhaust gas, distortion of ductwork and structural members, expansion-joint and penetrationseal failures, flying debris.

Metal-clad switchgear failure is characterized by

sudden noise, arc burn, flying molten metal, flying debris. Personnel should minimize the time they spend near this equipment, Anderson warned, and never attempt to close the switchgear on a load using the local controls on the front of the breaker enclosure.

Abnormal configurations. A powerplant typically is most hazardous when plant systems or personnel are in an abnormal configuration. During these times, the valve and equipment line-ups are generally unfamiliar to the plant staff, and also extremely



AMI Silica

Today's solution for online continuous measuring of silical in feed water, steam, condensate and make-up water

Automatic zero before every sample measurement.

LED photometer, long-term light source stability

A selectable measuring interval, low reagent consumption

Sample flow monitoring and low level reagents. detection

Measuring range up to 5,000 ppb

Optional dual sample stream or AMI Sample Sequencer available for up to six sample streams

> SWAN ANALYT CALUSA, Inc. 2251 arkin Drive, Unit 4, Wheeling, IL 50050 Phone 947 229 1290 Fax 847 229 1320 Info@swan analytical usa.com



(760) 525-3451, bob@bfsinc.org

complicated—creating conditions ripe for mishap—such as chemical releases, environmental spills, etc.

A hazard of abnormal plant configurations is the need to sometimes connect piping and equipment rated for different pressures. Equipment failure or inappropriate operation of these interconnections can quickly cause over-pressurization and catastrophic failure of the lower-pressure system. Examples here include auxiliary steam ties between units and ties among high-, intermediate-, and low-pressure boiler drains.

Anderson closed with several examples of abnormal plant configurations that have serious safety implications, requiring careful consideration and special procedures to prevent injury to plant and/or contractor personnel. They are:

- HRSG gas-path inspection with a nitrogen blanket on the steam side. Rigorous confined-space (gas side) air monitoring is important because an unknown tube leak could allow nitrogen to fill the lower gas-path spaces.
- Unusual rigging and lifting during major outages demands that your staff and contractor personnel take exclusion barricades seriously. Rotors have been known to drop. Also, before you install exclusion barricades, make sure all workers inside the barricaded area are escorted outside the barricades. Yes, there have been instances where people have been "barricaded in."
- Chemical cleaning of an HRSG demands a special safety review. With so much temporary piping, valves, heaters, and pumps, there's a significant risk of hot chemical leaks or spills.
- Repairing or replacing piping system components and welds opens a Pandora's box of safety issues, including high elevation or difficult access, additional risk of fire, additional risk of trips and falls because of cables and hoses for burning, welding, heat treating, etc.
- Reports of extreme weather conditions must always be taken seriously. High winds, rain or snow, ice, and extreme temperatures greatly increase the risks of slips and falls, risks from flying debris, risks of extreme worker fatigue, etc.

Leaving the podium, Anderson reminded the group that safety is a never-ending battle fought day-in and day-out. Ultimately, he said, it is your engaged and effective leadership that assures the well-being of all persons inside the plant fence, not corporate programs, catchy slogans, or cute posters hanging in the break room. CCJ



New website and forum at www.7Fusers.org

Your Steering Committee is developing a better website to serve both 7F users and their vendor business partners. Much work has been done already. We have improved the "look and feel" and are continually adding content that will bring value to owners and operators. Use of the website and forum are free and they are managed hands-on by your Steering Committee. Please visit www.7Fusers.org to see the improvements made. And while you are logged on, please re-register to be sure all the information we have for you is current.





Back row (I to r): Eugene Szpynda, NYPA; Jim Sellers, Entegra Power Group; Richard Clark, Southern California Edison; Ed Fuselier (Vice Chairman), Direct Energy; Jeff Gillis, ExxonMobil Chemical; Ken Gross, Con Edison. Front row: David Such, Xcel Energy; Dan Giel, Progress Energy; Sam Graham (Chairman), Tenaska; Ben Meissner, Progress Energy; Bob Holm, OxyChem; Paul White, Dominion Resources; Peter So (Treasurer), Calpine. Camera shy: Tom Berry, Tampa Electric; Art Hamilton, Calpine

Same organization planning the annual conferences

7F Users Group Inc. #412 2550 Sandy Plains Rd., Suite 225 Marietta, GA 30066 Sheila Vashi 7F Operations Manager 2550 Sandy Plains Rd., Suite 225 Office: 678-744-7373